



ENGINEERING

दक्षिण पूर्व मध्य रेलवे
SOUTH EAST CENTRAL RAILWAY
कार्यालय सहायक मंडल इंजी/1/भिलाई
Office of the: ADEN/I/BIA

75
आजादी का
अमृत महोत्सव

No. E/GAZ/BIA

Date :- 23.05.2023

To,
The Sr. DPO/Raipur
S.E.C.Railway

Sub:- Selection to the post of Technician – III (Welder) in pay Matrix Level -02 against 25% LDCE Quota in Engineering department of Raipur Division.


Ref:- E/PB/R/CON/2023/3, Dated – 08.05.23.

With reference to the above subject and under reference letter, joint representation from the candidates have been received to this office. In response to the above reference letter corrected/Revised answer key is enclosed here with in given format.

Sr. No.	Question No.	Original Question	Revised Question (if applicable)	Original Answer key provided for evaluation	Corrected/ Answer key	Remark
1	9	टाटा स्टील इस्पात संयंत्र भारत के किस राज्य में स्थित है। TATA steel plant located in which state of India.	Nil	(C)	(D)	
2	13	अवकाश वेतन के नगदीकरण के लिए न्यूनतम अवकाश शेष दिन होना चाहिए। For encasement of leave salary, minimum leave balance should be days.	Nil	(B)	--	Original key (B) is correct.
3	27	दो से कम बच्चों वाली महिला सरकारी सेविका को प्रसूति अवकाश स्वीकृत किया जा सकता है। Female Government servant with less than 02 children may be granted maternity leave for	Nil	(B)	(C)	
4	42	रेल टेंसर का उपयोग होता है। Rail tensor is used for	Nil	(B)	(A & B)	(A & B) Both are correct.
5	66	रेल तैयार करने के लिए सर्वोत्तम गुणवत्ता की कटिंग प्राप्त की जा सकती है। For rail preparation, Best quality cutting can be obtained by	Nil	(D)	(C & D)	(C & D) Both are correct. To be followed English version.
6	88	AT वेल्डिंग के मामले में के कारण फ्यूजन की कमी होती है। In case of AT welding, lack of fusion is caused due to	Nil	(B)	(B & D)	(B & D) Both are correct.
7	89	AT वेल्डिंग के मामले में, स्लैग समावेशन के कारण होता है। In case of AT welding, slag inclusion is caused due to	Nil	(D)	(C & D)	(C & D) Both are correct.

//2//

Sr. No.	Question No.	Original Question	Revised Question (if applicable)	Original Answer key provided for evaluation	Corrected/ Answer key	Remark
8	102	वाइड गैप वॉल्डिंग के लिए आवश्यक गैप 8..... Gap required for wide gap welding is.....	Nil	(A)	--	Original key (A) is correct.


ADEN/I/Bhilai
S.E.C.Railway