

**Addendum & Corrigendum No. 03 to General and Subsidiary
Rule Book 2013 of S. E. C. Railway.**

In the General & Subsidiary Rule Book : 2013

(1) The following SR 4.16.05 (a) is amended as follows :

SR 4.16.05 (a) :-

- (i) The red flag in lieu of Tail board or an unlit Tail lamp may be used only in exceptional circumstances with proper authorization.

- (ii) When an engine(s) is/are attached as the rear most vehicle of a train, and there is no provision to attach the Tail Board/Tail Lamp, the rear side marker light of the rear most engine should be illuminated with 'RED' light.**

In the event of such a contingency the section controller shall advise by a control order to all Station Masters on the section.

**(B.K.Joshi)
Chief Operations Manager
SECR/ BSP**

No. SEC/TRA/GSR/425/03/14

Dt. 03.06.14