

South East Central Railway



Office of the
Principal Chief Commercial Manager,
New Zonal Building, 1st floor 'D' Block
Bilaspur- 495004 (C.G)

Rates Circular No. 42 (G)/2018

No. C/SECR/BSP/Sdg/LPG BP/MNDH/1387

Date: 13.03.2018

All CSMs/SMs, CGSs/GSs, Goods Clerks, Weigh Bridge Clerks. CI/CCIs of SECR.

Copy for information and necessary action to:

DRM: SECR/BSP, NGP, RAIPUR. Sr. DCM & Sr.DOM: SECR/NGP, BSP, R. Commercial Control:

SECR/BSP: ARMs: SECR/BIA, KRBA, SDL & BRJN, Principal Director of Audit/SECR/BSP.

FA&CAO, COM, CFTM, SDGM, FA&CAO/(T), Dy.FA&CAO(T), Sr.AFA(TA): SECR/BSP.

CCM & COM: E.Rly-Kolkata, N.Rly-New Delhi, S.Rly-Chennai, W.Rly-CCG/Mumbai, C.Rly-CSTM/

Mumbai, N.F.Rly-Maligaon, N.E.Rly-Gorakhpur, N.C.Rly-Allahabad, E.Co.Rly-BBS, W.C.Rly-JBP,

N.W.Rly-Jaipur, S.W.Rly-Hubli, E.C.Rly-Hazipur, S.E.Rly-Kolkata, S.C.Rly-SC.

CONCOR/IISCO House, 50, Jawahar Lal Nehru Road, Kolkata.

GM/CRIS & CAO (FOIS), Center for Railway Information System, Chanakyapuri, New Delhi- 21.

Director, Traffic Commercial (Rates)/Railway Board/New Delhi.

EDRM/Rly. Board/ Eastern Railway House/Kolkata-01

Sub:- Introduction of "Round the Clock Working" at LBPM Siding/Mandirhasaud.

Ref:-1.CCM/E.Co.R/BSP's Commercial Circular No.211 (G)/07 vide No. CCM/Sdg/LPG/MNDH/Pt-I dtd.03.10.2007

2.This office Rates Circular No.8(G)/2016 dt.11.01.2016 (No.C/SECR/BSP/Sdg / LPG BP/MNDH/223

>>><<<

Reference is invited to CCM/ECOR's circular under reference wherein, the private siding of LPG Bottling Plant of HPCL (Alpha Code: LBPM) served by Mandirhasaud station was notified open for charging freight on through distance basis.

The through distance charging of freight of this siding was subsequently withdrawn vide this office Rates Circular under reference No.2 as shunting was involved at the time of placement and drawing-out of rakes and levy of siding charges was introduced. At present, the working hours of this siding is from 6:00 Hrs to 22:00 Hrs.

Now, with the approval of General Manager, "Round the Clock Working" has been introduced at this siding w.e.f. 15.03.2018.

The siding owner should provide mandatory facilities like lighting arrangement, adequate Fire Fighting Equipments. The staff posted must be well trained to use Safety Equipments.

(S.M.Gondane)

Dy. Chief Commercial Manager (FS)

For Principal Chief Commercial Manager

Copy to : The Chief Depot Manager, Hindustan Petroleum Corporation Ltd., Raipur IRD,
Mandir Hasaud, Distt. Raipur (C.G.) for information.