

**Addendum & Corrigendum No. 03 to General and Subsidiary
Rule Book 2013 of S. E. C. Railway.**


In the General & Subsidiary Rule Book : 2013

(1) The following SR 4.16.05 (a) is amended as follows :

SR 4.16.05 (a) :-

- (i) The red flag in lieu of Tail board or an unlit Tail lamp may be used only in exceptional circumstances with proper authorization.
- (ii) When an engine(s) is/are attached as the rear most vehicle of a train, and there is no provision to attach the Tail Board/Tail Lamp, the rear side marker light of the rear most engine should be illuminated with 'RED' light.

In the event of such a contingency the section controller shall advise by a control order to all Station Masters on the section.


(B.K.Joshi) 2/6
Chief Operations Manager
SECR/ BSP

No. SEC/TRA/GSR/425/03/14

Dt. 27.05.14
03.06.14

Circulations:

1. DRM/BSP, R & NGP.
 2. Sr. DSO, Sr. DSTE, Sr. DEN (Co-ord) /BSP, R & NGP.
 3. Sr. DOM, Sr. DME, Sr. DEE (OP)/ BSP, R & NGP.
- CFTM, CPTM, CTPM, CSO, CSTE, CEE, CE, CME, PCE/SECR/BSP.
STM/Plg., Principal- ZRTI/SINI, MDTC/BSP, ELTS/USL, STC/BIA & DTTC/DGG
Secy./SECR for kind information of GM.
Advisor (Safety)/ Rly. Bd., New Delhi.


Chief Operations Manager