

# संरक्षा विभाग / मुख्यालय SAFETY DEPARTMENT/HQ

दक्षिण पूर्व मध्य रेलवे, बिलासपुर (छ.ग.) 495004 SOUTH EAST CENTRAL RAILWAY, BILASPUR (C.G.) 495004

email: cso@secr.railnet.gov.in

एक कदम स्वच्छता की ओर

date: 30.09.2022

No.CSO/Safety/safety Circular/163

# Zonal Safety Circular No. - 12/2022

Sounding of Siren (Hooter) & Turning out of Relief Train/ARME Van.

## Para 7.01 (Accident Manual): Long Range Electric Sirens:

As a means of giving immediate warning to the staff of various departments in the event of an accident, a Long Range Electric Siren has been installed at each of the following stations of respective Divisions.

BSP Division			R Division			NAG Division		
S. N.	Station	Location (Hooter	S. N.	Station	Location (Hooter	S. N.	Station	Location (Hooter
		Operation)			Operation)			Operation)
1.	Bilaspur	Crew	1.	BMY	SM Panel	1.	Itwari	SM Panel
		Lobby			Room,			Room
2.	Shahdol	Crew			D-Cabin	2.	Gondia	Crew
		Lobby						Lobby
3.	Korba	Crew				3.	Chhindwara	Crew
		Lobby						Lobby
4.	Raigarh	SM Panel				4.	Nainpur	SM Panel
		Room						Room
5.	Manendragarh	SM Panel				5.	Motibagh	Diesel
		Room						Loco Shed
6.	Brajrajnagar	SM Panel						
		Room						

### Para 7.02 (Accident Manual): Accident Siren Code:

Sounding of Siren for tuning out of Relief Train/ARME van will be as follows:-

S.	Description of Accident	Total No.	Duration of	Gap between
N.		of Blast	each Blast	2 consequential Blast
1.	Relief Train with ARME	5	60 Seconds	10 seconds
2.	Relief Train without ARME	3	60 Seconds	10 seconds

The official in-charge of the 'Hooter' is responsible for proper maintenance b) of it and to keep a trained staff ready round the clock for sounding the hooter at once on receipt of orders from train order officials.

- c) Target time for the turnout of ARME and ART
  - i. The Accident Relief Medical Van must be despatched to the site of accident within 15 minutes from the base station after sounding the hooter where there is double exit siding and within 25 minutes in case of single exit siding with the first available engine.
  - ii. The Accident Relief Train must be turnout/despatched from the base station to the site of accident within 30 minutes by day and 45 minutes by night after sounding of hooter.

# Para 7.02.1 (Accident Manual):

In the event of the Long Range electric siren getting out of order, the emergency call shall be given by sounding the whistle of an engine as per the specific siren codes given in the table under para 7.02 above.

## **❖** Giving an Emergency Call (Sounding of Hooters):

- 1. As soon as information is received of an accident & there is requirement of Relief Train (ART/ARME), the Dy. CHC/Divisional Control shall take all possible action for arranging the movement of ARME/ART, as the case may be.
- 2. Dy.CHC/Divisional Control shall immediately inform SM of the Station where the ART/ARME is located for its immediate movement. Dy.CHC may also inform to Crew Controller of the lobby concerned for the same.
- 3. SM /Crew Controller available at such location shall immediately sound Hooter/Siren as per advice received for movement of ART/ARME.
- 4. SM and Crew Controller shall closely monitor for immediate dispatch of ART/ARMV within stipulated time frame.

(D. K. Singh)
Dy CSO(Traffic)
For, Principal Chief Safety Officer
S.E.C Railway/Bilaspur

#### Circulation to:

- 1. PCOM, PCEE & PCME for kind information.
- 2. DRM/BSP, R & NAG for information and necessary action.
- 3. All Branch Officers of BSP, R & NAG Division, for necessary action.
- 4. Sr.DSO/BSP, R & NAG for kind information and necessary action.
- 5. Principal, ELTC/USL, MDZTI/BSP for information and counselling to trainees.